

CASPIR Aircraft Accident Cards

Serial:	AK983
Title:	Curtiss Kittyhawk Mk. I serial:AK983 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1942-February-04. Kittyhawk s/n AK983. This accident involved 1 person. Russel BD
Keywords:	RCAFKittyhawk ,AK983,14 Sqn,14 Squadron,Ottawa River,1942-February-04,RusselRCAF L20
Created:	1942-02-04
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000961#AK983

TYPE OF A/C		PILOT		OTHERS		AIRFRAME FAILURE		ENGINE FAILURE	
UNIT 14 (F) Sqn. Rockcliffe		COM. # 3		PLACE Ottawa River		DATE 4-2-42		TIME 1645	
A/C TYPE Kittyhawk		No. AK983		CRASH CAT. C 2		SE x		ME	
NAME Russel, B.D.		RANK		No. C1319		DUTY FI		INJURIES Uninjured.	
SERIOUS		FATAL		INJURY		CARD SERIAL No.			
TYPE A/F & ENGINE Kittyhawk AK983		No. Allison 6311		EXTENT OF DAMAGE Slight		REPORT FORM		SERIAL No.	
A206615		Serious							
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE	
NATURE OF ACCIDENT									
STAGE OF FLIGHT		LANDING		TAKEOFF		FLIGHT		STATRY	
FATAL		INJURY		3RD.		RAF			

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

DATE:

COMPOSITION:

R.170

RECOMMENDATIONS:

Main fuel line rubber hose connection between emergency fuel pump and engine driven pump became disconnected. Due to improper installation at factory.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

All rubber hose connections thoroughly inspected.

~~All gas drained out of tanks.~~

RECORDED BY

DATE _____

CHECKED BY

DATE _____