CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: AJ824

Title: North American Harvard Mk. II serial:AJ824 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-March-07. Harvard II s/n AJ824. This accident involved 1 person. Over DH

Keywords: RAFHarvard II,AJ824,39 SFTS,39 Service Flying Training School,Aerodrome,1942-March-07,OverRCAF L20

Created: 1942-03-07

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ824

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

UNIT	COM.	PLACE	DATE	TIME
Swiftcurrent 39 S.F.T.S.	4	M.A.	7-3-42	1235

H.Q. FILE 1300-AJ824

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Harvard 11	AJ824	C5	x		x	

NAME	RANK	No.	DUTY	INJURIES	SERIOUS FATAL	SERIOUS INJURY
Over, D.H.	CPL.	549356	PP	Uninjured.		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE
Harvard11	AJ824	Slight			
Wasp S3H1	11377				
	A213658	Nil			

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO	LAST 6 MOS.
1	-	17	4	44	43	

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A-829 8-3-42					

NATURE OF ACCIDENT

TYPE OF A/C | TYPE OF ENGINE | CATEGORY | CAUSES | MISCELLANEOUS | FLIGHT | STAGE OF | INJURY

DUTY ON WHICH ENGAGED:

Completion of flight following practising of steep turn and aerobatics.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Faulty cockpit drill pupil failed to lower undercarriage.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

R.170

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Faulty vital actions Check.~~

(1)

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pupils Log Book endorsed by C.O.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C landed with undercarriage retracted.

(2)

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41