CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 5928

Title: de Havilland Moth, Tiger I serial:5928 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-March-02. Tiger Moth s/n 5928. This accident involved 1 person. Allen R

Keywords: RAFTiger Moth ,5928,33 EFTS,33 Elementary Flying Training School,Aerodrome,1942-March-02,AllenRCAF L20

Created: 1942-03-02

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5928

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:

[illegible]

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft Landed and collided with tractor engaged in rolling snow on airfield. The tractor driver instead of stopping thought he could improve the position by speeding up with the result that the a/c did run into the drag.

PRIMARY CAUSE:

~~Tractor driver speeded up his tractor and drag trying to dodge an aircraft.~~

6. Collision /

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pupil landed on line too close to path of drag assembly and collided.~~

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

R170

DATE: LCO/PSS/RCAM

COMPOSITION:

RECOMMENDATIONS:

Nil

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(1) Civilian tractor driver warned not to attempt aircraft dodging.

(2) Pupil's log book endorsed "Error in Judgment".

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41