CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 1750

Title: Fairey Battle Mk. I serial:1750 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-April-29. Fairey Battle s/n 1750. This accident involved 1 person. Sackett RC

Keywords: RCAFFairey Battle ,1750,4 BGS,4 Bomb & Gunnery School,Fingal Aerodrome,1942-April-29,SackettRCAF L20

Created: 1942-04-29

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000223#1750

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:

Returning to airdrome from Beam & Relative speed gunnery exercise.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot had completed gunnery exercise & was in circuit to land. Pilot had turned to approach the aerodrome when the engine failed and pilot executed a normal landing with U/C down.

PRIMARY CAUSE:

Engine failed, connecting rods breading.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

R.170

DATE:

COMPOSITION:

RECOMMENDATIONS:

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41