

CASPIR Aircraft Accident Cards

Serial:	AK968
Title:	Curtiss Kittyhawk Mk. I serial:AK968 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1942-April-10. Kttyhawk I s/n AK968. This accident involved 1 person. Ingalls JM
Keywords:	RCAFKttyhawk I,AK968,111 Sqn,111 Squadron,Patricia Bay,1942-April-10,IngallsRCAF L20
Created:	1942-04-10
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000961#AK968

PILOT		OTHERS		AIRFRAME FAILURE								ENGINE FAILURE											
CAUSES OF ACCIDENTS																							
UNIT 111 F. Sqdn. Patricia Bay				COM. # W.A.C.		PLACE No. 1 Runway Pat. Bay.						DATE 10-4-42		TIME 1145									
A/C TYPE Kittyhawk I				No. AK968		CRASH CAT. C		SE X		ME X		DAY X		NIGHT									
NAME Ingalls, J.M.				RANK P/O		No. J8357		DUTY PP		INJURIES Uninjured				SERIOUS FATAL INJURY									
														CARD SERIAL No.									
TYPE A/F & ENGINE Kittyhawk AK968		No. Allison 6268		EXTENT OF DAMAGE Serious Slight		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS											
												INST. NIGHT		ON TYPE DUAL SOLO		TOTAL DUAL SOLO		LAST 6 MOS.					
												27 10		--- 84		79 181							
SIGNAL No. & DATE A-644 10-4-42				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE			
NATURE OF ACCIDENT																							

DUTY ON WHICH ENGAGED:

Aircraft test.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

LUC/ODM

**Run after landing, starboard
undercarriage collapsed.**

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

**~~Failure of attaching nut on
starboard oleo leg.~~**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

17. Forced Landing

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**~~Belly landing due to undercarriage
failure.~~**

RECORDED BY

DATE

55. We expect

R.C.A.F. FORM 120 REQ. 1237 100-10-1741

CHECKED BY

DATE