CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: FD970

Title: Stearman Stearman (Kaydet) serial:FD970 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1942-May-30. They are: Stearman s/n FD972, Stearman s/n FD970. This accident involved 2 people. Bayetto P, Creal NR

Keywords: RAFStearman ,FD970,36 EFTS,36 Elementary Flying Training School,Aerodrome,1942-May-30,Bayetto,CrealRCAF L20

Created: 1942-05-30

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000947#FD970

CAUSES OF ACCIDENTS

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

32 JU. 31 TECH. 30 DISOB. 29 NEG'NCE 28 INEXP'NCE 27 MISCEL. 26 INSTRUCT. 25 FLT. CONTR. 24 OTHERS 23 PRIMARY 22 FL. CONTS. 21 MOV. SURFS. 20 STAB. SURFS. 19 W. STRUTS 18 LAND. GEAR 17 FLOATS 16 FUSE. OR HULL 15 TAIL SKID OR W. 14 ENGINE MOUNT. 13 MISCEL. 12 UND'TD 11 PRIMARY 10 FUEL SYS. 9 COOL. SYS. 8 IGNIT. SYS. 7 LUB'N SYS. 6 ENG. STR. 5 AIRSCREW A. 4 ENG. CONTS. 3 MISCEL. 2 UND'TD 1 PRIMARY

TYPE OF A/C

UNIT 36 E.F.T.S. Pearce, Alberta | COM. # 4 | PLACE Main Airdrome Pearce | DATE 30-5-42 | TIME 1430

A/C TYPE Stearman / Stearman | No. FD972 / FD970 - D | CRASH CAT. "B" / "C" | SE x / x | ME | DAY x | NIGHT

TYPE OF ENGINE

NAME	RANK	No.	DUTY	INJURIES
Creal, N.R.	P/O	116595	P	FD 970 Uninjured
~~Bayette, CRAUFORD Trevor~~	~~Sgt.~~		~~P~~	Uninjured
BAYETTO. P.	Sgt	522000	P	FD972 "

SERIOUS: FATAL | INJURY

CARD SERIAL No.

CAUSES

MISCELLANEOUS

CATEGORY

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE
Stearman	FD970				
Stearman	FD972				P.B

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO	LAST 6 MOS
		10	85	50	8	

STAGE OF FLIGHT

HAND Q. INSTS. WEATHER DRKNS. AL'G SURF. OTHER UND'TD PRIMARY TAXYING LANDING TAKE-OFF FLIGHT STAT'RY

INJURY: FATAL | INJ. | 3RD. | S | N

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A121 3-6-42					

NATURE OF ACCIDENT

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 RAF 32

DUTY ON WHICH ENGAGED:

Dual instruction.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft 972 Piloted by Sgt.Bayetto had the right of way but P.O. Creal failed to observe the other aircraft and taxied into the rear of it.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

DATE: TCA/[illegible]

COMPOSITION: TCA/[illegible]

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Carelessness on part of Creal.~~

COLLISIONS

9

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

P.O. Creal's log book endorsed "Carelessness."

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Collision between two aircrafts.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41