CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6675

Title: Avro Anson Mk. I serial:6675 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1942-July-29. They are: Anson I s/n 6397, Anson I s/n 6675. This accident involved 8 people. Garfield WV, Hind JDR, Holloram WR, Marshall JGS, Pocock FA, Preston W, Starrup BV, Wark TA

Keywords: RCAFAnson I,6675,1 CNS,1 Central Navigation School,Aerodrome,1942-July-29,Garfield, Hind,Holloram,Marshall,Pocock,Preston,Starrup,WarkRCAF L20

Created: 1942-07-29

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6675

CAUSES OF ACCIDENTS

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

PILOT: 32 PASS. 31 JU. 30 TECH. 29 DISOB. 28 NEG'NCE 27 INEXP'NCE 26 MISCEL.
OTHERS: 25 INSTRUCT. 24 FLT CONTR. 23 OTHERS
AIRFRAME FAILURE: 22 PRIMARY 21 FL. CONTS. 20 MOV. SURFS. 19 STAB. SURFS. 18 W. STRUTS 17 LAND GEAR 16 FLOATS 15 FUSE. OR HULL 14 TAIL SKID OR W. 13 ENGINE MOUNT. 12 MISCEL. 11 UND'TD
ENGINE FAILURE: 10 PRIMARY 9 FUEL SYS. 8 COOL. SYS. 7 IGNIT. SYS. 6 LUB'N SYS. 5 ENG. STR. 4 AIRSCREW A. 3 ENG. CONTS. 2 MISCEL. 1 UNK'TD ✓

MISCELLANEOUS CAUSES: 19 PRIMARY 18 HAND Q. 17 INSTS. 16 WEATHER 15 DRKNS. 14 A/G SURF. 13 OTHER 12 UND'TD 11

STAGE OF FLIGHT: 10 PRIMARY 9 TAXYING 8 LANDING 7 TAKE-OFF 6 FLIGHT 5 STAT'RY

INJURY: FATAL 4 INJ. 3 3RD. 2 N

UNIT	1 C.N.S.	COM.	# 2	PLACE	Main Aerodrome
	Rivers, Manitoba				
DATE	29-7-42	TIME	0830	H.Q. FILE	1100-66-75
A/C TYPE	Anson I	No.	6397 - D	CRASH CAT.	N/K
	Anson I		6675		B

SE	ME	DAY	NIGHT
	x	x	

NAME	RANK	NO.	DUTY	INJURIES	SERIOUS: FATAL	SERIOUS: INJURY
Pocock, F.A.	F/SGT	1334239	P	Uninjured		
Garfield, W.V.	LAC	1318021	NAV	"		
Starrup, B.V.	LAC	R125779	NAV	"		
Wark, T.A.	LAC	R66392	WO	"		
Hind, J.D.R.	SGT	657869	P	"		
Holloram, W.R.	LAC	R119691	NAV	"		
Marshall, J.G.S.	LAC	R129522	NAV	"		
Preston, W.	AC1	R71381	WO	"		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS: INST.	NIGHT	ON TYPE: DUAL	ON TYPE: SOLO	TOTAL: DUAL	TOTAL: SOLO	LAST 6 MOS.
Anson I	6675	Serious										
Cheetahs	AS13192/AS13589	Nil			FAP	30	21	170		271		
Anson	6397	Nil			JDRH	25	21	137		232		
Cheetahs	AS31234/AS13365	Nil										

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A-14 29-7-42					

NATURE OF ACCIDENT

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 RAF

TYPE OF A/C: 1 2 3 4 5 6 7
TYPE OF ENGINE: 1 2 3 4 5 6 7
CATEGORY: A B C D

R170

DUTY ON WHICH ENGAGED:

NAVIGATION FLIGHT (DAY)

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While waiting in line to take off on a regular Navigation Exercise Anson 6397 taxied into Anson 6675 cutting into the tail plane and rudder of 6675.

PRIMARY CAUSE:

~~Pilot of aircraft 6397 followed too closely behind aircraft 6675.~~

9. Collisions

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft 6397 taxied into 6675.~~

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

DATE:

COMPOSITION:

RECOMMENDATIONS:

Nil

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Definite instructions issued all pilots regarding taxiing. SGT. Hind reprimanded by Commanding Officer and his Log book endorsed and grounded for one week.

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41