CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 1920

Title: Fairey Battle Mk. I serial:1920 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-July-20. Fairey Battle s/n 1920. This accident involved 3 people. Beldone ENN, Haley FE, Russell G

Keywords: RCAFFairey Battle ,1920,5 BGS,5 Bomb & Gunnery School,Aerodrome,1942-July-20,Beldone,Haley,RussellRCAF L20

Created: 1942-07-20

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000223#1920

CAUSES OF ACCIDENTS

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

PILOT: PRIMARY, UND'TD
OTHERS: PRIMARY, FL. CONTS., MOV. SURFS., STAB. SURFS., W. STRUTS, LAND. GEAR, FLOATS, FUSE. OR HULL, TAIL SKID OR W., ENGINE MOUNT, MISCEL., UND'TD
AIRFRAME FAILURE: PRIMARY, FUEL SYS., COOL. SYS., IGNIT. SYS., LUB'N SYS., ENG. STR., AIRSCREW A., ENG. CONTS., MISCEL., UND'TD
ENGINE FAILURE: PRIMARY

MISCELLANEOUS CAUSES: HAND O., INSTS., WEATHER, DRKNS., A/G SURF., OTHER, UND'TD

STAGE OF FLIGHT: PRIMARY, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD

TYPE OF A/C: PUP, JU., TECH., DISOB., NEG'NCE, INEXP'NCE, MISCEL., INSTRUCT., FLT. CONTR., OTHERS

TYPE OF ENGINE

CATEGORY: A, B, C, D

UNIT	5 B & G School Dafoe, Sask.	COM.	2
PLACE	8 miles N.E. of M.A.		
DATE	20-7-42	TIME	1000
H.Q. FILE	1100-19-20		

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Battle	1920	C 3	x		x	

NAME	RANK	No.	DUTY	INJURIES	SERIOUS: FATAL	SERIOUS: INJURY
Haley F.E.	SGT.	R78405	PP	Uninjured.		
Beldone E.N.N.	LAC.	GB1387091	AB	"		
Russell G.	LAC.	GB658382	AB	"		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE
Battle	1920	Slight			
Merlin 541/8937		Nil			

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE: DUAL	ON TYPE: SOLO	TOTAL: DUAL	TOTAL: SOLO	LAST 6 MOS.
		2	101	2	101	
				383		

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A-33 20-7-42					

NATURE OF ACCIDENT

DUTY ON WHICH ENGAGED:

Scheduled bombing exercise.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine vibrated violently and a loud knocking sound developed. Pilot carried out "wheels up" landing in field.

PRIMARY CAUSE:

~~Engine failure occasioned by lack of compression.~~

18. Misc. Technical

19

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~"Wheels up" landing in field.~~

26. Engine trouble - Accident

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

R170

DATE:

COMPOSITION:

RECOMMENDATIONS:

Nil

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

RECORDED BY DATE

CHECKED BY DATE