CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: AJ793

Title: North American Harvard Mk. II serial:AJ793 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-19. Harvard II s/n AJ793. This accident involved 2 people. Matthew T, Sinclair GL

Keywords: RAFHarvard II,AJ793,39 SFTS,39 Service Flying Training School,Aerodrome,1942-August-19,Matthew,SinclairRCAF L20

Created: 1942-08-19

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ793

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

TYPE OF A/C | TYPE OF ENGINE | CATEGORY

MISCELLANEOUS CAUSES | STAGE OF FLIGHT

UNIT	COM.	PLACE	DATE	TIME
39 S.F.T.S. Swift Current	4	½ mile N.W. of M.A.	19-8-42 1300-AJ793	2025

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Harvard II	AJ793	C 14	x		x	

NAME	RANK	No.	DUTY	INJURIES	SERIOUS: FATAL	SERIOUS: INJURY
Sinclair G.L. GB	F/L	41478	F.J.	Slightly injured.		1
Matthew T.	P/O	544445	F.J.	Uninjured.		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS: INST.	NIGHT	ON TYPE: DUAL	ON TYPE: SOLO	TOTAL: DUAL	TOTAL: SOLO	LAST 6 MOS.
Harvard II	AJ793	Slightly.										
Wasp S3H1	11340/A	213626 Slightly.				42	58	1	161	97	735	
						38	29	62	209	197	385	

SIGNAL No. & DATE	UNIT No & DATE	COM. No & DATE	REPORT	FILE	DATE
A-266 20-8-42					

NATURE OF ACCIDENT

DUTY ON WHICH ENGAGED:
Collection of record of forced landed A/C.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C overturned on landing through hitting boulder.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: LCO/ATO/PCL/XGR ✓ R.170

DATE:

COMPOSITION:

RECOMMENDATIONS:
NiL.

PRIMARY CAUSE:
Carelessness.
J. Olmes

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Pilot interviewed by Chief Instructor. Log Book endorsed "Carelessness".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:
~~A/C hit boulder and overturned.~~

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41