CAUSES OF ACCIDENTS

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

PILOT: P, JU., TECH., DISOB., NEG'NCE, INEXP'NCE, MISCEL.
OTHERS: INSTRUCT., FLT. CONTR., OTHERS
AIRFRAME FAILURE: PRIMARY, FL. CONTS., MOV. SURFS., STAB. SURFS., W. STRUTS, LAND. GEAR, FLOATS, FUSE. OR HULL, TAIL SKID OR W., ENGINE MOUNT, MISCEL., UND'TD
ENGINE FAILURE: PRIMARY, FUEL SYS., COOL. SYS., IGNIT. SYS., LUB'N SYS., ENG. STR., AIRSCREW A., ENG. CONTS., MISCEL., UND'TD

MISCELLANEOUS CAUSES: PRIMARY, HAND Q., INSTS., WEATHER, DRKNS., A/G'S SURF., OTHER, UND'TD

STAGE OF FLIGHT: TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD., N-

TYPE OF A/C | TYPE OF ENGINE | CATEGORY

UNIT	COM.	PLACE	DATE	TIME
4 S.F.T.S Saskatoon, Sask.	# 2	H 2.	16-9-42	0820

H.Q. FILE 1100-77-69

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Crane I	7769	C 3		x	x	

NAME	RANK	No.	DUTY	INJURIES	SERIOUS: FATAL	SERIOUS: INJURY
Burton, R.A.J.	P/O	J10584	F.I.	Uninjured.		
Webber, R.C.	LAC	R124445	PP	Uninjured.		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE
Crane I	7769	Slightly.			
Jacobs L4MB	4694/22113	NiL.			
	943/21091	NiL.			

HOURS FLOWN BY PILOTS

	INST.	NIGHT	ON TYPE: DUAL	ON TYPE: SOLO	TOTAL: DUAL	TOTAL: SOLO	LAST 6 MOS.
	36	25	14	25	17	44	
	-	-	3	-	24	33	

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
D 162 17-9					

NATURE OF ACCIDENT

DUTY ON WHICH ENGAGED:

Dual circuits and landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Overshot slightly on landing. Ran past boundary markers and struck rock.

PRIMARY CAUSE:

~~Error of judgment on part of pilot.~~

Overshot

(1)

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Ran past boundary markers on landing run and struck rock hidden by grass.~~

Nil.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

R.170

DATE:

COMPOSITION:

10/4/43

RECOMMENDATIONS:

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NiL.

RECORDED BY _____ DATE

CHECKED BY _____ DATE