CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: P5433

Title: Handley Page Hampden Mk. I serial:P5433 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-October-17. Hampden s/n P5433. This accident involved 1 person. Roscorla HE

Keywords: RAFHampden ,P5433,32 OTU,32 Operational Training Unit,Patricia Bay Aerodrome,1942-October-17,RoscorlaRCAF L20

Created: 1942-10-17

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000845#P5433

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:

General flying practice.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Swung after landing, resulting in collapse of starboard undercarriage. A/C ground looped.

PRIMARY CAUSE:

Error of judgment.

Swing.

2

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pilot ~~failed to correct swing, he did not use brakes to keep straight, STBD U/C collapsed and A/C ground looped.~~

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

D-14

DATE:

COMPOSITION: L S / PSS / USS

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Further demonstration and instruction in use of rudder and brakes in landing.
Pilots log book endorsed.

RECORDED BY DATE

CHECKED BY DATE