CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 8964

Title: de Havilland Moth, Tiger I serial:8964 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-October-17. Tiger Moth s/n 8964. This accident involved 1 person. Atherton RC

Keywords: RCAFTiger Moth ,8964,4 EFTS,4 Elementary Flying Training School,Aerodrome,1942-October-17,AthertonRCAF L20

Created: 1942-10-17

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#8964

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:

Take-offs and landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Tire blew on take-off the right. wing dropped and A/C swerved just as it was airborne, when attempting to land on the left wheel, A/C bounced, left wing hitting ground.

PRIMARY CAUSE:

~~Inexperience of the pilot.~~

Heavy

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Blown tire, bounce on landing and dropping left wing tip.~~

Tire burst

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

D-14

DATE:

COMPOSITION: LUC/UTD

RECOMMENDATIONS:

Nil.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

RECORDED BY DATE

CHECKED BY DATE