CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6589

Title: Avro Anson Mk. I serial:6589 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-January-22. Anson I s/n 6589. This accident involved 5 people. Alsop PW, Borum JW, Frost TF, Graham JB, Schellenberg W

Keywords: RCAFAnson I,6589,1 CNS,1 Central Navigation School,Virden,1943-January-22,Alsop,Borum,Frost,Graham,SchellenbergRCAF L20

Created: 1943-01-22

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6589

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:

Proceeding to scene of forced landing at Fort Quappelle, Sask.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Forced landed with wheels up, after one engine cut out and the other was running very poorly.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

A.O.P.D.14

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~54. Engine failure in the air.~~

(17)

17. Forced Landing

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Engine failure. Letting down with motors idling thus allowing them to get cold.~~

(26)

26. Engine Trouble - Accident

RECORDED BY DATE

CHECKED BY DATE