CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 4060

Title: de Havilland Moth, Tiger I serial:4060 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-May-29. Tiger Moth s/n 4060. This accident involved 1 person. Poirier JHA

Keywords: RCAFTiger Moth ,4060,2 EFTS,2 Elementary Flying Training School,Aerodrome,1943-May-29,PoirierRCAF L20

Created: 1943-05-29

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#4060

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:
Solo seq. 6,7,8. authorized.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D-14 #108

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Pupil pilot taxiing back for take-off was watching another A/C and taxied into boundary light.

DATE:
COMPOSITION: T.D. /12

RECOMMENDATIONS:

PRIMARY CAUSE:
~~2. Hitting obstructions.~~
Collisions

9

ACTION TAKEN:
(A) Disciplinary (B) Technical (C) Other
Log book endorsed "carelessness" and pilot admonished.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:
~~24. Carelessness.~~

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41