CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 10705

Title: Fairchild Cornell Mk. II serial:10705 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-June-10. Cornell II s/n 10705. This accident involved 2 people. Mortimer AC, Rawson CA

Keywords: RCAFCornell II,10705,2 FIS,2 Flying Instructor School,Aerodrome,1943-June-10,Mortimer,RawsonRCAF L20

Created: 1943-06-10

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#10705

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
2 F.I.S. Pearce, Alta.	4	M.A.	1-6-43	1645

H.Q. FILE 1100-107-05

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
Cornell 11	10705	C 1	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Rawson, C.A.	F/O	J12089	FI	NiL.
Mortimer, A,C. GB	S/D	1324953	PP	NiL.

SIGNAL

NO.	DATE
A223	12-6

D 14 (REVISED)

NO.	CHECKED
2	√

#11

ENGINE	ENGINE NUMBER(S)
Ranger 6333/27540	NiL.

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
-	-	107	7	1811	120
-	-	4	5	107	140

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE OFF
FLIGHT
STATRY

INJURY: FATAL, INJ., 3RD, S

RAF, M, N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:
Instruction.

NATURE OF ACCIDENT:
A/C collided with steam roller while taxiing in heavy rain and poor visibility.

TECHNICAL OFFICER'S REPORT:
NiL. T.O.'s Report Received

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS: SUMMARY No.

CLASSIFICATION:
~~2. Hitting obstructions.~~ 9
9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:
~~32. Pilot error.~~

ACTION TAKEN:
NiL.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43