CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 7334

Title: Avro Anson Mk. II serial:7334 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-June-08. Anson II s/n 7334. This accident involved 4 people. Hann LR, Hales EM, Black AH, Barber TA

Keywords: RCAFAnson II,7334,4 BGS,4 Bomb & Gunnery School,Aerodrome,1943-June-08,Barber,Black,Hales,HannRCAF L20

Created: 1943-06-08

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7334

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
4 B.G.S. Fingal	1	M.A.	8.6.43	1030

H.Q. FILE 1100-72-34

A/C TYPE	No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
Anson II	7334	C.4		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Black, A.H.	PO	C2012	P	Nil
Hann, L.R. (GB)	LAC	1587040	PP	Nil
Hales, E.M. (GB)	LAC	1601704	PP	Nil
Barber, T.A.	Cpl	R221025	Pass.	Nil

SIGNAL

NO.	DATE
A.51	9.6

D 14 (REVISED)

NO.	CHECKED
2	✓

#10

ENGINE	ENGINE NUMBER (S)
Jacobs	16936/3115 NiL.
	17357/3536 NiL.

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
41	1	52	10	210	159

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, 5

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:
Routine bombing exercise.

NATURE OF ACCIDENT:
Tail wheel assembly collpased on landing.

TECHNICAL OFFICER'S REPORT:
Landing with tire failure caused the fitting between tail oleo and tail wheel post to break.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS: SUMMARY No.

CLASSIFICATION:
~~33. Technical defect.~~
V/C. FAILURE
(5)

SECONDARY OR CONTRIBUTORY FACTORS:
TAIL WHEEL
(38)

ACTION TAKEN:
NiL.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43