CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: BW775

Title: Lockheed Hudson Mk. III serial:BW775 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-03. Hudson III s/n BW775. This accident involved 2 people. Collins TH, Fotheringham-parker J

Keywords: RAFHudson III,BW775,36 OTU,36 Operational Training Unit,Aerodrome,1943-June-03,Collins,Fotheringham-parkerRCAF L20

Created: 1943-06-03

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000890#BW775

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
No.36 O.T.U. Greenwood, N.S.	EAC	MA.	3-6-43	1430 ADT

H.Q. FILE: 1300-BW775

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
Hudson III	BW775	B		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Fotheringham-Parker, J.R.A.F.	F/O	114317	FI	Nil
Collins, T.H.	P/O	J24378	PP	Nil

SIGNAL

NO.	DATE
A798	3-6

D 14 (REVISED)

NO.	CHECKED
	4

No. 2

ENGINE	ENGINE NUMBER (S)
W.Cyc. GR.1820	P.A258088
G.205A	S.A210957

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
98	80	340	17	858	51
30	18	-	1	102	88

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S, N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Giving initial dual to pupil pilot.

NATURE OF ACCIDENT:

On coming in to land the wheels of the A/C struck a ridge of sand at the end of the runway which damaged the port leg, causing it to collapse.

TECHNICAL OFFICER'S REPORT:

No technical failure involved.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~41. Hitting obstructions.~~ 6

COLLISIONS

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

W/C STRAIN 34

ACTION TAKEN:

NIL

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43