CASPIR.warplane.com

# CASPIR Aircraft Accident Cards

**Serial:** 6138

**Title:** Avro Anson Mk. I serial:6138 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-July-26. Anson I s/n 6138. This accident involved 1 person. Forbes JR

**Keywords:** RCAFAnson I,6138,10 AOS,10 Air Observer School,Aerodrome,1943-July-26,ForbesRCAF L20

**Created:** 1943-07-26

**Link:** https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6138

ACCIDENT CLASSIFICATION

| UNIT | COM. | PLACE | DATE | TIME |
|---|---|---|---|---|
| No.10 A.C.S. Chatham, N.B. | # 3 | N.B. | 26-7-43 | 2355 |

H.Q. FILE 1100-61-38

| A/C TYPE | NO. | CRASH CAT. | S.E. | M.E. | DAY | NIGHT |
|---|---|---|---|---|---|---|
| Anson I | 6138 | B | | X | | X |

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES |
|---|---|---|---|---|
| Forbes, J.R. | SGT | R132043 | P | Nil |

SIGNAL

| NO. | DATE |
|---|---|
| A637 | 27-7 |

D 14 (REVISED)

| NO. | CHECKED |
|---|---|
| | |

No.14

| ENGINE | ENGINE NUMBER (S) |
|---|---|
| Cheetah IX | P.230082/A584126 S.11146/A823042 |

HOURS FLOWN BY PILOTS

| INST. | NIGHT | ON TYPE | | TOTAL | |
|---|---|---|---|---|---|
| | | SOLO | DUAL | SOLO | DUAL |
| 43 | 19 | 112 | 13 | 204 | 104 |

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STATRY

INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:
Night landing practice.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:
Stbd. tire blew out on take-off. A/C had attained a speed of approx. 50 mph. Pilot was unable to keep A/C straight resulting in a ground loop.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS: 05/[illegible] SUMMARY No.

CLASSIFICATION:
~~15. Tire failure.~~
12. Swung. (12)

SECONDARY OR CONTRIBUTORY FACTORS:
~~38. Ground Loop~~
37. Tire Burst (37)

ACTION TAKEN:
NIL

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 505
H. Q. 885-L 20

C. C. LTD. 7084-43