CASPIR.warplane.com

# CASPIR Aircraft Accident Cards

**Serial:** 4675

**Title:** Fleet Finch Finch II serial:4675 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-July-11. Fleet Finch II s/n 4675. This accident involved 1 person. Lambert F

**Keywords:** RCAFFleet Finch II,4675,11 EFTS,11 Elementary Flying Training School,Aerodrome,1943-July-11,LambertRCAF L20

**Created:** 1943-07-11

**Link:** https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000720#4675

ACCIDENT CLASSIFICATION

| UNIT | COM. | PLACE | DATE | TIME |
|---|---|---|---|---|
| 11 E.F.T.S. Cap De La Ladeleine | 3 | L.A. | 11-7-43 | 1430 |

H.Q. FILE 1100-/6-75

| A/C TYPE | NO. | CRASH CAT. | S.E. | M.E. | DAY | NIGHT |
|---|---|---|---|---|---|---|
| Fleet Finch II | 4675 | C 1 | x | | x | |

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES |
|---|---|---|---|---|
| Lambert, F. | LAC | 1672257 | PP | Nil |

SIGNAL: NO. L.462 DATE 11-7

D 14 (REVISED) NO. 6 CHECKED X

12

| ENGINE | ENGINE NUMBER (S) |
|---|---|
| Kinner B5 | 6071/1409 Nil |

HOURS FLOWN BY PILOTS

| INST. | NIGHT | ON TYPE SOLO | ON TYPE DUAL | TOTAL SOLO | TOTAL DUAL |
|---|---|---|---|---|---|
| | | 1 | 8 | 1 | 20 |

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STATRY

INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo Seq. 6-7-8

NATURE OF ACCIDENT:

On landing, right wing dropped, applied right rudder at first and then applied left rudder, causing A/C to keel over on left wing tip, causing noseup.

TECHNICAL OFFICER'S REPORT:

Nil LH/[redacted]

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~61. Swinging on landing~~

2. [redacted]

SECONDARY OR CONTRIBUTORY FACTORS:

~~25. Inexperience~~

~~36. Mosing up~~

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43