CASPIR.warplane.com

# CASPIR Aircraft Accident Cards

**Serial:** 8921

**Title:** de Havilland Moth, Tiger I serial:8921 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 2 aircraft on 1943-July-02. They are: Tiger Moth s/n 8987, Tiger Moth s/n 8921. This accident involved 1 person. Parker EVJ

**Keywords:** RCAFTiger Moth ,8921,4 EFTS,4 Elementary Flying Training School,Aerodrome,1943-July-02,ParkerRCAF L20

**Created:** 1943-07-02

**Link:** https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#8921

ACCIDENT CLASSIFICATION

| UNIT | COM. | PLACE | DATE | TIME |
|---|---|---|---|---|
| 4 E.F.T.S. Windsor Mills | 3 | M.A. | 2.7.43 | 0845 |

H.Q. FILE 1100-89-87

| A/C TYPE | NO. | CRASH CAT. | S.E. | M.E. | DAY | NIGHT |
|---|---|---|---|---|---|---|
| T/Moth<br>T/Moth | 8987-D<br>8921 | A<br>C.2 | X | | X | |

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES |
|---|---|---|---|---|
| Parker, E.V. J. | LAC | R182459 | PP | Nil |

SIGNAL

| NO. | DATE |
|---|---|
| A74 | 2.6 |

D 14 (REVISED)

| NO. | CHECKED |
|---|---|
| W.M.2 | ✓ |

3

| ENGINE | ENGINE NUMBER (S) | |
|---|---|---|
| G.Major | 12832/89014 | Serious |
| | 1489/89355 | Nil |

HOURS FLOWN BY PILOTS

| INST. | NIGHT | ON TYPE | | TOTAL | |
|---|---|---|---|---|---|
| | | SOLO | DUAL | SOLO | DUAL |
| :15 | | 5 | 17 | 5 | 17 |

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STATRY

INJURY: FATAL, INJ., 3rd D, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo circuits

NATURE OF ACCIDENT:

A/C took off slightly out of wind, commenced swerving to stbd., failed to correct with rudder. A/C headed for parking line and became airborne, struck stbd. wing of 8921 on line, cartwheeled and was demolished.

TECHNICAL OFFICER'S REPORT:

OCA/PSJ

Nil

MA./KB

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~9. Swinging~~

12. Swing

(12)

SECONDARY OR CONTRIBUTORY FACTORS:

~~10. Hitting other aircraft~~

~~25. Inexperience~~

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43