CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6449

Title: Avro Anson Mk. I serial:6449 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1943-August-24. They are: Anson I s/n 4861(Listed as N4861), Anson I s/n 6449. This accident involved 4 people. Baigent CH, Ritchie SE, Keane NF, Stevenson DB

Keywords: RCAFAnson I,6449,7 AOS,7 Air Observer School,Aerodrome,1943-August-24,Baigent,Keane,Ritchie,StevensonRCAF L20

Created: 1943-08-24

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6449

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 AOS Portage la Prairie	2	M.A.	24-8-43	1330

H.Q. FILE 1100-48-61

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I ANSON I	4861 D 6449	"D" 2½ Nil		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Ritchie, S.E.	Sgt	R11994	P	Uninj.
Saigent, C.H.	Lac	R415169	N	Uninj.
Stevenson, D.B.	Lac	R431332	N	Uninj.
Keane, M.F NZ	P/O	422994	WAG	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
3	✓

#16

ENGINE	ENGINE NUMBER (S)
Cheetah IX	228714/AS32758 Nil 228619/AS32663 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
38	253	589	34	722	128

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATY
FATAL
INJ.
3RD
S
INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigational training flight.

NATURE OF ACCIDENT:

Brake cable broke while a/c taxiing out on parking strip. A/C swung across runway, stbd. wing striking bow end of a/c 6449. damaging

TECHNICAL OFFICER'S REPORT:

Ball pulled out of the end of cable

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

Nil
T-9/6 11
11/6 9

CLASSIFICATION:

~~7. Brake failure.~~
9. Collision (9)

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a/c~~
36. Brake Failure (36)

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43