CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 8422

Title: Avro Anson Mk. II serial:8422 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-August-26. They are: Anson II s/n 8434, Anson II s/n 8422. This accident involved 1 person. Lippard DCW

Keywords: RAFAnson II,8422,38 SFTS,38 Service Flying Training School,Aerodrome,1943-August-26,LippardRCAF L20

Created: 1943-08-26

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8422

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
38 S.F.T.S. Estevan	2	M.A.	26-8-43	1800-43

H.Q. FILE 1100-84-34

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II D ANSON II	8434 8422	"D"1 Nil		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Lippard, D.C.W.	Lac	1800237	PP	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
5	✓

#60

ENGINE	ENGINE NUMBER (S)	
Jacobs L6MB	17564/9033	Nil
	14137/25448	Nil
	25407/9777	Nil
	25165/9535	Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
11	5	14	20	49	55

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY

INJURY
FATAL
INJ.
3RD
S

RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Local solo practices.

NATURE OF ACCIDENT:

Collided with parked a/c 8422 while taxiing.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

3. Hitting other a/c

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed "Carelessness" and grounded for 1 month

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43