CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 8931

Title: de Havilland Moth, Tiger I serial:8931 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-August-21. Tiger Moth s/n 8931. This accident involved 1 person. Wallace WWS

Keywords: RCAFTiger Moth ,8931,4 EFTS,4 Elementary Flying Training School,Richmond Lake,1943-August-21,WallaceRCAF L20

Created: 1943-08-21

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#8931

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
4 E.F.T.S. Windsor Mills	3	North shore Richmond lake	21-8-43	1625

H.Q. FILE 1100-89-31

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
TIGER MOTH	8931	"B"	X		X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Wallace, W.W.S.	Lac	R125529	PP	Uninj.

SIGNAL: NO. A.81 DATE 22-8

D 14 (REVISED) NO. CHECKED ✓

#45

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
Gipsy Major I	1443/39350	3	-	23	24	23	24

TYPE OF A/C | TYPE OF UNIT | CATEGORY

COMMAND | MONTH | STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Practice aerobatics, steep turns and spins.

TECHNICAL OFFICER'S REPORT:

nil

NATURE OF ACCIDENT:

Engine failed on third loop. Love to get motor restarted and lost height Motor started at 1500' for short time. Forced landed in field striking tree

ILFM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~5. Engine failure in air.~~

17. Forced Landing (17)

SECONDARY OR CONTRIBUTORY FACTORS:

~~1. Hitting obstacles.~~

~~25. Inexperience.~~

26. Engine trouble - Accident

ACTION TAKEN:

nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43