CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6085

Title: Avro Anson Mk. I serial:6085 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-September-29. Anson I s/n 6085. This accident involved 4 people. Knowles W, Mcneil DH, Dobson AR, Johnson JD

Keywords: RCAFAnson I,6085,1 CNS,1 Central Navigation School,Yorkton,1943-September-29,Dobson,Johnson,Knowles,McneilRCAF L20

Created: 1943-09-29

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6085

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 C.N.S. Rivers	2	18 Miles S Yorkton	29-9-43	2330

H.Q. FILE: 1100-60-85

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6085	"B"		x		x

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
McNeil, D.H.	SGT	R156832	P	Uninj.
Dobson, A.R.	F/S	R116474	WAG	Uninj.
Knowles, W. GB	CPL	539206	OC	Uninj.
Johnson, J.D. GB	LAC	610280	OC	Uninj.

SIGNAL

NO.	DATE
A.220	30-9

D 14 (REVISED)

NO.	CHECKED
3	K

#11

ENGINE	ENGINE NUMBER (S)
Cheetah IX	PAS31915 slightly S11308/AS31630 "

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
49	68	171	4	275	142

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE OFF
FLIGHT
STAT'RY
FATAL
INJ.
3RD
S
INJURY

RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Failure of Port motor on a night navigation exercise, necessitating a forced landing. A/C would not maintain altitude on stbd motor.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air.~~

17. Engine trouble

Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

~~34. Wheels up landing.~~

~~41. Hitting obstructions.~~

26. Engine trouble.

ACTION TAKEN:

Nil

R. C. A. F. 1120 (REVISED)
7M-4-43 (6202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43