CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6944

Title: Avro Anson Mk. I serial:6944 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-October-04. Anson I s/n 6944. This accident involved 5 people. Frankland N, Kittleson ME, Mckay DC, Ross EC, Wilson DE

Keywords: RCAFAnson I,6944,1 CNS,1 Central Navigation School,Broadview Saskatchewan,1943-October-04,Frankland,Kittleson,Mckay,Ross,WilsonRCAF L20

Created: 1943-10-04

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6944

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 C.N.S. Rivers	2	Broadview, Sask.	4-10-43	1645.

H.Q. FILE 1100-69-44

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6944	~~Nil~~ D		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Ross, E.C.	SGT	R166317	P	Uninj.
McKay, D.C.	P/O		OC	Uninj.
Wilson, D.E.	SGT	R164133	OC	Uninj.
Kittleson, M.E.	SGT	RR78242	OC	Uninj.
Frankland, N.	LAC	R166361	WOG	Uninj.

F.L.

SIGNAL

NO. DATE

D 14 (REVISED)

NO. CHECKED X

#8

ENGINE	ENGINE NUMBER (S)	
Cheetah IX	10145/AS30504	Nil
	11502/AS31860	Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
42	63	208	4	311	140

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STAT'RY

INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Port engine failed, symptons of which were very rough running of motor, which continued despite manipulation of mixture control. Took precaution of landing at nearest airport.

TECHNICAL OFFICER'S REPORT:

Cylinder locking ring failed on #5 cylinder.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43