ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
41 S.F.T.S. Weyburn	2	R2 Ralph	15-10-43	1500
			H.Q. FILE	1300-FE351

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
HARVARD	FE351	"C"7	X		X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Abrahams, J.A.	SGT	1062671	FI	Uninj.
Jump, F.	LAC	1624978	PP	Uninj.

SIGNAL	
NO.	DATE
A.186	16-10
D 14 (REVISED)	
NO.	CHECKED
6	✓
#73	

ENGINE	ENGINE NUMBER (S)
Wasp AN-1	15771/42-635 Slightly

HOURS FLOWN BY PILOTS					
INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
45	52	420	94	455	170

TYPE OF A/C — TYPE OF UNIT — CATEGORY — COMMAND — MONTH — STAGE OF FLIGHT — FORCED LANDING — TAXYING — LANDING — TAKE-OFF — FLIGHT — STAT'RY — FATAL — INJ. — 3RD — S — INJURY — RAF — M — N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Pracautionary landing demonstration

NATURE OF ACCIDENT:

Instructor undershot on approach and struck embankment of road along northern boundary of R.2, Ralph

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

LU/PSU

CLASSIFICATION:

30. Undershooting runway.

3

SECONDARY OR CONTRIBUTORY FACTORS:

41. Hitting obstructions.

32. Pilot error.

ACTION TAKEN:

Log book endorsed "Error of Judgment".

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43