CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 5984

Title: de Havilland Moth, Tiger I serial:5984 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-October-10. Tiger Moth DH82C s/n 5984. This accident involved 1 person. Watters G

Keywords: RCAFTiger Moth DH82C,5984,4 EFTS,4 Elementary Flying Training School,Aerodrome,1943-October-10,WattersRCAF L20

Created: 1943-10-10

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5984

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
4 E.F.T.S. Windsor Mills	3	M.A.	10-10-43	1500

H.Q. FILE 11[illegible]0-59-84

A/C TYPE	No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
TIGER MOTH 82C	5984	"C"I	X		X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Watters, G. GB	LAC	1567058	PP	Uninj.

SIGNAL

No.	DATE
A.85	11-10

D 14 (REVISED)

No.	CHECKED
1	

#19

ENGINE	ENGINE NUMBER (S)
Gypsy Major	1-C 2463/89306 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
1	-	4	13	4	1331

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Flying training seq. 10,11,12.

TECHNICAL OFFICER'S REPORT:

Nil.

NATURE OF ACCIDENT:

Swung on landing right wing touching ground & a/c nosed up.

L5/1155

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

61. Swinging on landing 2

SECONDARY OR CONTRIBUTORY FACTORS:

36. Nosing up.
25. Inexperience.

ACTION TAKEN:

Log book endorsed

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43