CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11228

Title: Avro Anson Mk. II serial:11228 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-November-02. Anson II s/n 11228. This accident involved 3 people. Stout AO, Billinge LK, Allport AD

Keywords: RCAFAnson II,11228,1 NAGS,1 Naval Air Gunnery School,Aerodrome,1943-November-02,Allport,Billinge,StoutRCAF L20

Created: 1943-11-02

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11228

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 N.A.G. Yarmouth	E	M.A.	2-11-43	1600 AWT

H.Q. FILE 1100-112-28

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11228	" "		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Stout, A.O. NZ	SGT	421541	P	Uninj.
Billince, L.K.	ALA	86800	AG	Uninj.
Allport, A.D.	ALA	426677	AG	Uninj.

SIGNAL

NO.	DATE
T.663	2-11

D 14 (REVISED)

NO.	CHECKED
1	X

#3

ENGINE	ENGINE NUMBER (S)
Jacobs L6MB	14591/11582 slightly
	14590/11581 "

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
-	-	67	2	274	121

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S, I

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

T.A.G. training.

NATURE OF ACCIDENT:

Taxiing down taxi strip wind swung a/c, port brake failed to prevent a/c going off taxi strip and down embankment.

TECHNICAL OFFICER'S REPORT:

7A/U 01

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~7. Brake failure.~~ 9

9. Collision

SECONDARY OR CONTRIBUTORY FACTORS:

1. ~~Bad surface of a-rodrome.~~

36 Brake Failure 36

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43