CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: R9800 (formerly 9800)

Title: Avro Anson Mk. I serial:R9800 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-November-04. Anson I s/n R9800 (formerly 9800). This accident involved 4 people. Beattie J, Turnbull JW, Mckinnon DJ, Buchanan DM

Keywords: RCAFAnson I,R9800 (formerly 9800),1 CNS,1 Central Navigation School,Portage Airport,1943-November-04,Beattie,Buchanan,Mckinnon,TurnbullRCAF L20

Created: 1943-11-04

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#R9800

ACCIDENT CLASSIFICATION

UNIT 1 C.N.S. RIVERS MAN.	COM. 2	PLACE Portage Airport	DATE 4-11-43	TIME 16:30
			H.Q. FILE 1100-98-00	

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	9800	[illegible]		M.E.	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
BEATTIE, J. GB	LAC	156544	Nav.	Uninj.
MCKINNON, D.J.	SGT	R171504	P	Uninj.
BUCHANAN, D.M. GB	LAC	156783	Nav.	Uninj.
TURNBULL, J.W.	AC2	R196379	WOG	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
2	#5

ENGINE	ENGINE NUMBER (S)
CHEETAH IX	P10431/AS30783 S11004/AS31721

HOURS FLOWN BY PILOTS					
		ON TYPE		TOTAL	
INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
38	59	253	95	283	135

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT RY

INJURY
FATAL
INJ
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:
Navigation Exercise.

NATURE OF ACCIDENT:
Starboard engine trouble due to defective valves.

TECHNICAL OFFICER'S REPORT:
Stbd motor exhaust valve swallowed on No. 2 Cylinder.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS: SUMMARY No.

CLASSIFICATION:
33 Technical defect.

SECONDARY OR CONTRIBUTORY FACTORS:
54 Engine failure in the air.

ACTION TAKEN:
Nil.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43