CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11320

Title: Avro Anson Mk. II serial:11320 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-November-10. Anson II s/n 11320. This accident involved 3 people. Alcorn WB, MacDougall AG, Madowell JC

Keywords: RCAFAnson II,11320,17 SFTS,17 Service Flying Training School,Aerodrome,1943-November-10,Alcorn,MacDougall,MadowellRCAF L20

Created: 1943-11-10

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11320

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.E.T.S. Souris	2	M.A.	10-11-43	1640
			H.Q. FILE	1100-113-20

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11320	"C"1		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Alcorn, W.B.	F/S	R151018	P	Uninj.
McDowell, J.C.	LAC	R200038	PP	Uninj
MacDougall, A.H.	LAC	R200033	PP	Uninj.

SIGNAL

NO.	DATE
A.86	11-11

D 14 (REVISED)

NO.	CHECKED
#4	X

#28

ENGINE	ENGINE NUMBER (S)
Jacobs L6.1.B	P.26167/10871 NIL
	S.26164/10868 NIL

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
34	43	422	113	455	153
12	5	7	20	47	59
11	5	6	21	46	57

TYPE OF A/C
TYPE OF UNIT
CATEGORY
COMMAND
MONTH
STAGE OF FLIGHT
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation Exercise.

NATURE OF ACCIDENT:

One propellor Blade damaged. Nature of accident unknown. Noticed nothing wrong with the a/c except that on last leg of the exercise, to. syonchronize the engines was difficult.

TECHNICAL OFFICER'S REPORT: Port propellor damaged not repairable this unit. One blade only was damaged. Unable to definitely establish cause of damage. The Accident Investigation Branch to investigate further.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~57. Miscellaneous.~~ 24

24 Prop. etc.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43