CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 3845

Title: de Havilland Moth, Tiger I serial:3845 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-November-21. Tiger Moth s/n 3845. This accident involved 1 person. Wheately GC

Keywords: RCAFTiger Moth ,3845,2 EFTS,2 Elementary Flying Training School,Kakabeka Field,1943-November-21,WheatelyRCAF L20

Created: 1943-11-21

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#3845

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
2 E.F.T.S. Fort William	2	Kakabeka field	21-11-43	1045
			H.Q. FILE	1100-38-45

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
TIGER MOTH	3845	"D"	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Wheately, G.C. GB	LAC	1605637	PP	Slightly Inj.

SIGNAL

NO.	DATE
A.126	22-11

D 14 (REVISED)

NO.	CHECKED
3	✓

#33

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Gipsy Major	13001/89441 slightly	-	-	4	28	4	28

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY

INJURY
FATAL
INJ.
3RD
S
N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Authorized solo practice of Seq. 10,11,12,13,17.

NATURE OF ACCIDENT:

Student practising turns, had difficulty in recovering from turn with bad slip. He recovered near ground became frightened and landed in FLF. A/C overturned when wheels struck a snow bank.

CLASSIFICATION:

~~37. Overturning.~~ 7

7. Other

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

~~44. Bad surface.~~

TECHNICAL OFFICER'S REPORT:

NIL

LBG/[illegible]

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

ACTION TAKEN:

Being progress tested.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43