CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 7531

Title: Avro Anson Mk. II serial:7531 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-December-17. Anson II s/n 7531. This accident involved 3 people. Beland RA, Long RR, Loveland HA

Keywords: RCAFAnson II,7531,4 BGS,4 Bomb & Gunnery School,Aerodrome,1943-December-17,Beland,Long,LovelandRCAF L20

Created: 1943-12-17

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7531

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
4 B.G.S. Fingal	1	M.A.	17-12-43	1230
			H.Q. FILE	1100-75-31

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	7531	"D"5		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Beland, R.A.	F/S	R82661	P	Uninj.
Long, R.R. GB	LAC	1800876	AB	Uninj.
Loveland, H.A.	LAC	R189958	AB	Uninj.

SIGNAL

NO.	DATE
R.86	17-12

D 14 (REVISED)

NO.	CHECKED

44

ENGINE	ENGINE NUMBER (S)	
Jacobs L-6MB	16450/2629	Nil
	16713/2892	Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
51	47	450	19	712	13

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Routine Bombing Exercises.

NATURE OF ACCIDENT:

While a/c was being parked, tail wheel fell into hole in frozen ground.

TECHNICAL OFFICER'S REPORT:

Failure of lower longerons between stations Y and B adjacent to station Y. (Ref. CAP 218 Vol.1 Sec. 7 Chap.1 Figure 1)

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

Remarks of Unit C20.
Warning flag not set up at frozen rut by A.O.C.
Closer supervision of aerodrome surface to be kept.

CLASSIFICATION:

~~1. Bad surface of aerodrome.~~ 10

10. Bad Ground

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil.

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43