CASPIR.warplane.com

# CASPIR Aircraft Accident Cards

**Serial:** 11352

**Title:** Avro Anson Mk. II serial:11352 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-December-27. Anson II s/n 11352. This accident involved 2 people. Adolphe DG, Wildgen HE

**Keywords:** RCAFAnson II,11352,17 SFTS,17 Service Flying Training School,R1 Hartney,1943-December-27,Adolphe,WildgenRCAF L20

**Created:** 1943-12-27

**Link:** https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11352

ACCIDENT CLASSIFICATION

| UNIT | COM. | PLACE | DATE | TIME |
|---|---|---|---|---|
| 17 S.F.T.S. Souris | 2 | R1 Hartney | 27-12-43 | 1515 |
| | | | H.Q. FILE | 1100-113-52 |

| A/C TYPE | NO. | CRASH CAT. | S.E. | M.E. | DAY | NIGHT |
|---|---|---|---|---|---|---|
| ANSON II | 11352 | "D"1 | | x | x | |

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES |
|---|---|---|---|---|
| Adolphe, D.G. | F/S | R106410 | FI | Uninj. |
| Wildgen, H.E. | LAC | R197429 | PP | Uninj. |

| SIGNAL NO. | SIGNAL DATE |
|---|---|
| A.123 | 28-12 |

D 14 (REVISED)

| NO. | CHECKED |
|---|---|
| 8 | ✓ |

#53

| ENGINE | ENGINE NUMBER (S) | |
|---|---|---|
| Jacobs L6MB | 26331/14817 | Nil |
| | 26330/14816 | Nil |

HOURS FLOWN BY PILOTS

| INST. | NIGHT | ON TYPE SOLO | ON TYPE DUAL | TOTAL SOLO | TOTAL DUAL |
|---|---|---|---|---|---|
| 65 | 134 | 777 | 32 | 996 | 191 |
| 7 | 5 | - | 8 | 5 | 43 |

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT RY

INJURY
FATAL
INJ.
3RD
S
L
N

RAF
M

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Instructing of flying sequences.

NATURE OF ACCIDENT:

After completion of precautionary landing, instructor raised flaps without coming to a stop and opened throttles to take-off again. Raised the u/c before a/c was airborne and the a/c settled to the ground.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~8. U/C retracted too soon.~~ 16

16. Others

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

33 U/C Pull - Ex Grace 33

ACTION TAKEN:

Log book endorsed and disciplinary action taken against pupil.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43