CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: FH942

Title: Fairchild Cornell Mk. I serial:FH942 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-December-12. Cornell I s/n FH942. This accident involved 2 people. Doswell ME, Harris AH

Keywords: RAFCornell I,FH942,33 EFTS,33 Elementary Flying Training School,Rowletta,1943-December-12,Doswell,HarrisRCAF L20

Created: 1943-12-12

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#FH942

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
33 E.F.T.S. Caron	4	3 miles NE OF Rowletta	12-12-43	1200
			H.Q. FILE	1300-FH942

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
CORNELL I	FH942	"D"	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Harris, A.H.	SGT	1582124	FI	Uninj.
Doswell, M.N.	LAC	1607714	PP	Uninj.

SIGNAL NO.	SIGNAL DATE
C.281	13-12

D 14 (REVISED)

NO.	CHECKED
#7	✓

#32

ENGINE	ENGINE NUMBER (S)
Ranger 6-440-C5	27994/6053

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
45	50	482	128		

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
INJURY
FATAL
INJ.
3RD
S

PURPOSE OF FLIGHT:

Forced landing practice.

NATURE OF ACCIDENT:

Carrying out forced landing practice, opened up engine which spluttered. Lost height. Tried to avoid a post, engine picked up. Turned to left, then wing struck wire.

TECHNICAL OFFICER'S REPORT:

NIL. ILCO/RCAJ

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air.~~ 22

22. Collisions - Obstns

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

Reproof of instructor. Warning to all instructors in Flying Detail on proper appreciation of cold weather conditions.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43