CASPIR.warplane.com

# CASPIR Aircraft Accident Cards

**Serial:** FH925

**Title:** Fairchild Cornell Mk. I serial:FH925 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-December-29. Cornell I s/n FH925. This accident involved 1 person. Bartlett C

**Keywords:** RAFCornell I,FH925,33 EFTS,33 Elementary Flying Training School,Aerodrome,1943-December-29,BartlettRCAF L20

**Created:** 1943-12-29

**Link:** https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#FH925

ACCIDENT CLASSIFICATION

| UNIT | COM. | PLACE | DATE | TIME |
|---|---|---|---|---|
| 33 E.F.T.S. Caron | 4 | N.A. | 29-12-43 | 1030 |

H.Q. FILE: 1300-FH925

| A/C TYPE | NO. | CRASH CAT. | S.E. | M.E. | DAY | NIGHT |
|---|---|---|---|---|---|---|
| CORNELL I | FH925 | "D 1" | x | | x | |

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES |
|---|---|---|---|---|
| Bartlett, C. | SGT | 510003 | P | Uninj. |

SIGNAL

| NO. | DATE |
|---|---|
| C.287 | 30-12 |

D 14 (REVISED)

| NO. | CHECKED |
|---|---|
| 9 | ✓ |

#64

| ENGINE | ENGINE NUMBER (S) |
|---|---|
| Ranger 6-440-C5 | 28137/6196 Nil |

HOURS FLOWN BY PILOTS

| INST. | NIGHT | ON TYPE SOLO | ON TYPE DUAL | TOTAL SOLO | TOTAL DUAL |
|---|---|---|---|---|---|
| 7 | 5 | 29 | 31 | | |

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ, 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

NATURE OF ACCIDENT:

A/C was parked on tarmac without chocks, and with brakes incorrectly applied. It moved forward and stnuck boundary fence.

TECHNICAL OFFICER'S REPORT:

Nil

TCO /

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~17. Disobedience of Standing Orders.~~ (9)

9. Collision

SECONDARY OR CONTRIBUTORY FACTORS:

~~2. Hitting obstructions.~~

24 ~~Carelessness.~~

ACTION TAKEN:

Log book endorsed and disciplinary action taken.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43