CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 4060

Title: de Havilland Moth, Tiger I serial:4060 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-December-10. Tiger Moth s/n 4060. This accident involved 2 people. Kadwell AW, Mclare E

Keywords: RCAFTiger Moth ,4060,2 EFTS,2 Elementary Flying Training School,Aerodrome,1943-December-10,Kadwell,MclareRCAF L20

Created: 1943-12-10

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#4060

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
2 E.F.T.S. Fort William	2	5 miles W of M.A.	10-12-43	1435

H.Q. FILE 1100-40-60

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
TIGER MOTH	4060	"3"	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
McLare, E.	F/S	R159113	FI	Uninj.
Kadwell, A.W.	LAC	R209041	PP	Uninj.

SIGNAL

NO.	DATE
A.140	13-12

D 14 (REVISED)

NO.	CHECKED
	✓

20

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Gipsy Major	7491/85402 Seriously	54	68	451	51	569	168
		4	1	20	32	20	32

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S, N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Autherized Dual instruction Seq. 14, 16, 17, 22.

NATURE OF ACCIDENT:

Engine failed at approximately 300' away from forced landing field. After working throttle and losing altitude the motor came on again at full R.P.M. then died again to an uneven splutter with not enough R.P.M. to maintain height. Pilot was forced to attempt landing in area thick with growth of trees and brush. He managed to slip into a small clearing, struck snow covered stump and overturned.

CLASSIFICATION:

~~54. Engine failure in the air.~~ 17

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

16 Engine Trouble - Accident

26

TECHNICAL OFFICER'S REPORT:

Icing in carburettor caused motor to quit.

1LFM/30/F S/[illegible]/11/2015

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

ACTION TAKEN:

Nil.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43