CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: N5361

Title: Avro Anson Mk. I / IV serial:N5361 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-January-07. Anson IV s/n N5361. This accident involved 4 people. Bennett DT, Griffiths RD, Holman FS, Kennedy GA

Keywords: RCAFAnson IV,N5361,1 AOS,1 Air Observer School,Aerodrome,1944-January-07,Bennett,Griffiths,Holman,KennedyRCAF L20

Created: 1944-01-07

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#N5361

ACCIDENT CLASSIFICATION

UNIT 1 A.O.S. MALTON	COM. 1	PLACE M.A.	DATE 7-1-44	TIME 21:25	
			H.Q. FILE 1300-N5361		
A/C TYPE ANSON IV		NO. N. 5361	CRASH CAT. "A"	S.E.	M.E.
				DAY	NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
GRIFFITHS, R.D.	SGT	134292	P	Uninj.
HOLMAN, F.S.	LAC	R217383	1 Nav	Uninj.
BENNETT, D.T.	LAC	R209358	2 Nav	Uninj.
KENNEDY, G.A.	SGT	R193138	WAG	Uninj.

SIGNAL

NO.	DATE
M5	8-1-44

D 14 (REVISED)

NO.	CHECKED
	✓

#6

ENGINE	ENGINE NUMBER (S)
Wright	18987/43496
Whirlwind	15171/18814

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
60	99	463	52	592	155

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:
Night navigation.

NATURE OF ACCIDENT:
Pilot just taking off - a/c about 10' in air when port engine stopped. Pilot pulled on carburetter heat and tried to pick it up with no success, so cut other throttle and landed straight ahead. Night was bright, with snow on ground and excellent visibility.

TECHNICAL OFFICER'S REPORT:
That either a partial or full stoppage of gas resulted between outer tank and carburetter, causing failure through this medium or through an air lock in fuel lines.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS:

SUMMARY No.

DFM/AEP/ES/Reports

CLASSIFICATION:
~~13. Engine failure.~~
15. Forced Land (15)

SECONDARY OR CONTRIBUTORY FACTORS:
26. Engine trouble - accident (26)

ACTION TAKEN:
Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43