CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6864

Title: Avro Anson Mk. I serial:6864 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-March-09. Anson I s/n 6864. This accident involved 4 people. Blowers RL, Foulds JM, Murray LS, Scott GR

Keywords: RCAFAnson I,6864,7 AOS,7 Air Observer School,Stockton,1944-March-09,Blowers,Foulds,Murray,ScottRCAF L20

Created: 1944-03-09

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6864

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 A.O.S. Portage la Prairie	2	4 miles S of Stockton	9-3-44	1455

H.Q. FILE 1100-68-64

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6864	"E"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
MURRAY, L.S.	SGT	R155298	P	Uninj.
SCOTT, G.R.	LAC	R160451	NAV	Uninj.
FOULDS, J.M.	LAC	R223830	NAV	Uninj.
BLOWERS, R.L. GB	LAC	954742	AB	Uninj.

SIGNAL

NO.	DATE
No sig	

D 14 (REVISED)

NO.	CHECKED
3	✓

#11

ENGINE	ENGINE NUMBER (S)
Cheetah IX	13357/AS32198
	10359/AS30854 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
65	153	457	143	479	177

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STAT RY

FATAL

INJ.

3RD

S

INJURY

RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Low level navigation exercise.

NATURE OF ACCIDENT:

While on low level exercise port motor failed. A/C would not hold altitude on single engine long enough to reach Souris airport, causing pilot to make "Belly" landing in field.

TECHNICAL OFFICER'S REPORT:

Cuttings found in screens.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43