CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11498

Title: Avro Anson Mk. II serial:11498 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-March-15. Anson II s/n 11498. This accident involved 1 person. Westwood G

Keywords: RCAFAnson II,11498,17 SFTS,17 Service Flying Training School,Aerodrome,1944-March-15,WestwoodRCAF L20

Created: 1944-03-15

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11498

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.F.T.S. Souris	2	M.A.	15-3-44	1230
			H.Q. FILE	1100-114-98

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11498	"D"2		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
WESTWOOD, G.	LAC	R258391	PP	Uninj.

SIGNAL

NO.	DATE
A.82	15-3

D 14 (REVISED)

NO.	CHECKED
4	✓

#21

ENGINE	ENGINE NUMBER (S)
Jacobs L6MB	17747/9120 Nil
	15569/1757 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
13	4	8	17	44	49

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ
3RD
S
N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Single engined practice.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Student approached for a single engine landing. Warming dud motor and cutting out horn each time he closed throttle. During approach leg the control tender fired three red flares and the control tower fired one. Student continued his approach and landed on belly.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

34. Wheels up landing.

17

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed and 168 hours detention. Transfer to course 102.

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H.Q. 885-L 20

C. C. LTD. 7084-43