CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 3949

Title: de Havilland Moth, Tiger I serial:3949 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1944-March-02. They are: Tiger Moth s/n 1116, Tiger Moth s/n 3949. This accident involved 2 people. Chambers RG, Lennox RC

Keywords: RCAFTiger Moth ,3949,4 EFTS,4 Elementary Flying Training School,Aerodrome,1944-March-02,Chambers,LennoxRCAF L20

Created: 1944-03-02

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#3949

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
4 E.F.T.S. Windsor Mills	3	M.A.	2-3-44	0830

H.Q. FILE 1100-11-16

A/C TYPE	No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
TIGER MOTH	1116 D	"C"1	/		X	
TIGER MOTH	3949	"C"1				

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
CHAMBERS, R.G.	F/O	J23015	FI	Uninj.
LENNOX, R.C.	LAC	R213325	PP	Uninj.

SIGNAL

NO.	DATE
A.20	

D 14 (REVISED)

NO.	CHECKED
1	✓

#1

ENGINE	ENGINE NUMBER (S)
Gipsy Major	2419/89192 Nil
	~~2408/89215~~ Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
72	108	1093	39	1666	166
4	-	18	21	18	21

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Dual instructions.

TECHNICAL OFFICER'S REPORT: Nil

TCA/PCT
NIL
[redacted] MH/xA

NATURE OF ACCIDENT:

While taxxing into the line cross-wind on skiis, the a/c began to slide downhill toward another a/c, Since there was no one present to hold pilot's wingtip, he attempted to swing a/c into wind with a burst of throttle.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Hitting other a/c.
9

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed "Carelessness" and logged.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43