CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: HJ882

Title: de Havilland Mosquito T.Mk. III serial:HJ882 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-March-04. Mosquito TIII s/n HJ882. This accident involved 2 people. Bouton WE, Kernaghan SJ

Keywords: RAFMosquito TIII,HJ882,36 OTU,36 Operational Training Unit,Aerodrome,1944-March-04,Bouton,KernaghanRCAF L20

Created: 1944-03-04

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001095#HJ882

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
36 O.T.U. Greenwood	E	M.A.	4-3-44	0905

H.Q. FILE 1300-HJ882

A/C TYPE	No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
MOSQUITO TIII	HJ882	"A"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
KERNAGHAN, S.J.	F/O	J17176	P	Uninj.
BOUTON, W.E.	F/O	J22711	PP	Uninj.

SIGNAL

NO.	DATE
A.383	4-3

D 14 (REVISED)

No.	CHECKED
1	✓

#1

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Rolls Royce Merlin	256764/72915 Nil	22	23	50	2	630	105
	256669/72725 Nil	53	80	-	2	780	150

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY: FATAL, INJ, 3RD, S, RAF, M, Z

PURPOSE OF FLIGHT:

Dual instructions.

NATURE OF ACCIDENT:

Port wheel struck frozen snow bank at end of runway just before touch-down and collapsed on touch down.

TECHNICAL OFFICER'S REPORT:

NIL

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~30.~~ 3 Undershooting runway.

SECONDARY OR CONTRIBUTORY FACTORS:

~~24.~~ Carelessness.

ACTION TAKEN:

Log book endorsed "Carelessness".

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43