CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 15198

Title: Fairchild Cornell Cornell III serial:15198 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-April-09. Cornell II s/n 15198. This accident involved 1 person. Burton RAJ

Keywords: RCAFCornell II,15198,24 EFTS,24 Elementary Flying Training School,Aerodrome,1944-April-09,BurtonRCAF L20

Created: 1944-04-09

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#15198

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
24 E.F.T.S. Abbotsford	4	M.A.	9-4-44	1530

H.Q. FILE 1100-151-98

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
CORNELL II	15198	"D"	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
BURTON, R.A.J.	F/O	J10584	P	Uninj.

SIGNAL: NO. No sig; DATE

D 14 (REVISED) NO. 2 CHECKED

#26

ENGINE	ENGINE NUMBER (S)
Ranger	37399/6915 Nil

HOURS FLOWN BY PILOTS					
INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
70	130	250	30	1500	175

TYPE OF A/C | TYPE OF UNIT | CATEGORY | COMMAND | MONTH | STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY | INJURY: FATAL, INJ., 3RD, S, N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Instructor practice.

TECHNICAL OFFICER'S REPORT:

TUC/UDM

NATURE OF ACCIDENT:

Pilot taxied out prior to take-off and upon turning into wind preparatory to running up engine, stbd oleo leg snapped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~28. Structural failure~~. (8)

8. M/C Failure

SECONDARY OR CONTRIBUTORY FACTORS:

39 Structural Failure (39)

ACTION TAKEN:

NIL

R. C. A. F. C. 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43