ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
3 S.F.T.S. Calgary	4	1½ miles NW of Careland	8-4-44	1615
			H.Q. FILE 1100-80-72	

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
CRANE I	8072	F/L	x	x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
ROSS, J.C.	P/O	J37036	P	Uninj.
FARNHAM, B.H. AUS	LAC	439463	PP	Uninj.

SIGNAL NO.	DATE
A.22	10-4

D 14 (REVISED)

NO.	CHECKED
2	✓

#3

ENGINE	ENGINE NUMBER (S)	
Jacobs L4MB	21914/4895	serious
	22307/8358	Nil

HOURS FLOWN BY PILOTS	INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
	49	29	267	124	310	179
	8	-	9	15	34	50

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STAT'RY

INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Routine training flight.

NATURE OF ACCIDENT:

Instructor pilot of a/c 8072 was demonstrating precautionary landing to student when port engine failed. A/C was close to ground and airspeed was low, so pilot made forced landing straight ahead.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

NIL

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

ACTION TAKEN: