CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 712

Title: Hudson III serial:712 - Crash Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-April-25. Hudson III s/n 712. This accident involved 6 people. Cook GM, Luscott WC, O'Sullivan HP, Smith EC, Snyder WS, Soper JH

Keywords: RCAFHudson III,712,11 Sqn,11 Squadron,Torbay,1944-April-25,Cook,Luscott,O'Sullivan,Smith,Snyder,SoperRCAF L20

Created: 1944-04-25

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
No. 11 Sqdm. Torbay, Nfld.	EAC	TORBAY	25-4-44	1145

H.Q. FILE

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
HUDSON III	712	"B"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Cook, G.M.	W/C	C1059	P	Uninj.
Snyder, W.S.	F/L	J25558	NAV	Uninj.
O'Sullivan, H.P.	P/O	J41969	WAG	Uninj.
Luscott, W.C.	LAC		Pass	Uninj.
Dr. E.C. Smith	ORS		Pass	Uninj.
Dr. J.H. Soper	ORS		Pass	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED

#4

ENGINE	ENGINE NUMBER (S)
Wright Cyclone	A211278/ S.39486 P.39562

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
92	193	329	6	2014	98

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S
NIL

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Demonstration of Rocket Weapon

NATURE OF ACCIDENT:

Throttle stuck part way open on landing resulting in ground loop at end of landing run.

TECHNICAL OFFICER'S REPORT: LO/AMM

Small piece of Flexiglass became jammed under throttle

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

33. ~~Technical defect.~~ (2)

J. Swing

SECONDARY OR CONTRIBUTORY FACTORS:

38. ~~Ground loop~~.

ACTION TAKEN:

NIL

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43