CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6137

Title: Avro Anson Mk. I serial:6137 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-May-02. Anson I s/n 6137. This accident involved 3 people. Allman FR, Donahue JL, Hayes HJ

Keywords: RCAFAnson I,6137,4 BGS,4 Bomb & Gunnery School,Lucan,1944-May-02,Allman,Donahue,HayesRCAF L20

Created: 1944-05-02

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6137

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
4 B.G.S. Fingal	1	2 miles S of Lucan	2-5-44	1645

H.Q. FILE: 1100-61-37

A/C TYPE	No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6137	"C"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
DONAHUE, J.L.	P/O	J29351	P	Uninj.
ALLMAN, F.R.	CPL	R156349	PP	Uninj.
HAYES, H.J.	CPL	R152213	PP	Uninj.

SIGNAL: NO. No sig; DATE

D 14 (REVISED) NO. CHECKED

#6

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
Cheetah	229570/AS33614 slight 11496/A 25012 "	65	18	521	99	548	224

TYPE OF A/C

TYPE OF UNIT

CATEGORY: A B C D

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S, N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Pilot flying navigation exercise at 2000'. Ran outer tanks until stbd engine sputtered. Stbd engine failed to pick up when change to inner stbd tank was made. Pilot reports no full pressure on this tank indicated. Port outer cock jammed, making it impossible to switch port engine to inner tank. Port engine failed due to lack of fuel and pilot made procedure wheels up landing in best available field. When checked after accident port outer gas cock was found to jam 3 inches from top of slide.

CLASSIFICATION:

~~33. Technical defect.~~ (18) Misc. Technical

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

NIL FB/HOP/PLDE/FE/PM/UH/FT/PH/UOKE

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

NIL

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43