CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11462

Title: Avro Anson Mk. II serial:11462 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-May-13. Anson II s/n 11462. This accident involved 2 people. Brennan JB, Muncaster DA

Keywords: RCAFAnson II,11462,17 SFTS,17 Service Flying Training School,Aerodrome,1944-May-13,Brennan,MuncasterRCAF L20

Created: 1944-05-13

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11462

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.F.T.S. Souris	2	M.A.	13-5-44	1315

H.Q. FILE: 1100-114-62

A/C TYPE	No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11462	"D"5		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
BRENNAN, J.B.	P/O	J39587	P	Uninj.
MUNCASTER, D.A.	LAC	R264108	PP	Uninj.

SIGNAL: No. A126 — Date 14-5

D 14 (REVISED): No. 4 — CHECKED ✓

#25

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
Jacobs L6MB	26278/10982 Nil	42	32	163	127	210	170
	15373/25684 Nil	10	6	-	2	37	39

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY · INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Dual seq.

NATURE OF ACCIDENT:

A/C left parking line, proceeding to taxi downwind on tarmac. A/C developed a swing to left. Instructor took control and applied right brake and port engine. Brakes poor on right side. A/C cut across lawn and collided with hangar.

TECHNICAL OFFICER'S REPORT: Tech I/UBF

NIL Tco/Pt1/UBF

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~8. Hitting obstructions.~~
9 Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

~~36. Brake failure.~~
~~32. Pilot error.~~
36. Brake Failure

ACTION TAKEN:

Log book endorsed.

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H.Q. 865-L 20

C.C. LTD. 7084-43