CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6721

Title: Avro Anson Mk. I serial:6721 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-May-30. Anson I s/n 6721. This accident involved 4 people. Elsande , Fenn , Passmore LW, Round

Keywords: RCAFAnson I,6721,7 AOS,7 Air Observer School,Aerodrome,1944-May-30,Elsande,Fenn,Passmore,RoundRCAF L20

Created: 1944-05-30

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6721

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
# 7 A.O.S.	2	M.A.	30-5-44	0930
			H.Q. FILE	1100-67-21

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6721	"E"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Passmore, L.W.	Civ		P	Nil
Fenn, GB	LAC	1649200	1stN	"
Round, GB	LAC	1152407	2ndN	"
Elsande,	LAC	K270662	AB	"

SIGNAL

NO.	DATE
No sig.	

D 14 (REVISED)

NO.	CHECKED
4	

28

ENGINE	ENGINE NUMBER (S)
Cheetah IX	11117/AS31715 10942/AS31645

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
34	659	1439	47	1519	65

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:
Day Nav. exercises.

NATURE OF ACCIDENT:
Drop in oil pressure stbd engine-engine and engine controls were normal before failure.

TECHNICAL OFFICER'S REPORT:
Failure of seal between capillary line and Banjo allowing oil to leak out resulting in fluctuating of oil pressure.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS: SUMMARY No.

CLASSIFICATION:
54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:
Nil.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43