CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: AX244

Title: Avro Anson Mk. I serial:AX244 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-May-30. Anson IV s/n AX244. This accident involved 3 people. Gladish WJ, Rowe WC, Smith IF

Keywords: RCAFAnson IV,AX244,1 AOS,1 Air Observer School,Aerodrome,1944-May-30,Gladish,Rowe,SmithRCAF L20

Created: 1944-05-30

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#AX244

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 A.C.S. Malton	1	M.A.	30-5-44	0945

H.Q. FILE 1300-AX244

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON IV	AX244	'C'		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
GLADISH, W.J.	F/ET	C4434	OC	Uninj.
ROWE, W.C.	SGT	R191655	P	Uninj.
SMITH, I.F.	SGT	R163191	2P	Uninj.

SIGNAL

NO.	DATE
M485	30-5

D 14 (REVISED)

NO.	CHECKED

#2

ENGINE	ENGINE NUMBER (S)
Wright Whirlwind	18735/43254 serious 18992/43507

HOURS FLOWN BY PILOTS	INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
	61	25	9	27	105	155
	57	26	8	22	102	143

TYPE OF A/C
TYPE OF UNIT
CATEGORY
COMMAND
MONTH
STAGE OF FLIGHT
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
S
INJURY
RAF
M

PURPOSE OF FLIGHT:

Pilot and second pilot were being checked on bombing prodedure by Armament officer.

NATURE OF ACCIDENT:

Port tire blew on take-off, pilot cut throttles, applied full opposite rudder and brake. A/C struck Department of Transport transformer pit, just off edge of runway. A/C ground looped. Left wing badly damaged, left u/c collapsed, left propellor damaged.

TECHNICAL OFFICER'S REPORT:

NIL

OUC UTB

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

M. ~~Tire failure.~~

16 Others

SECONDARY OR CONTRIBUTORY FACTORS:

37. Tyre Burst

ACTION TAKEN:

NIL

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43