CASPIR.warplane.com

# CASPIR Aircraft Accident Cards

**Serial:** 6089

**Title:** Avro Anson Mk. I serial:6089 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-June-01. Anson I s/n 6089. This accident involved 4 people. Moorehead CA, Pufall JH, Slade B, Warder AJ

**Keywords:** RCAFAnson I,6089,7 AOS,7 Air Observer School,Aerodrome,1944-June-01,Moorehead,Pufall,Slade,WarderRCAF L20

**Created:** 1944-06-01

**Link:** https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6089

ACCIDENT CLASSIFICATION

| UNIT | COM. | PLACE | DATE | TIME |
|---|---|---|---|---|
| 7 A.O.S. Portage la Prairie | 2 | M.A. | 1-6-44 | 2245 |

H.Q. FILE 1100-60-89

| A/C TYPE | NO. | CRASH CAT. | S.E. | M.E. | DAY | NIGHT |
|---|---|---|---|---|---|---|
| ANSON I | 6089 | "E" | | x | | x |

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES |
|---|---|---|---|---|
| MOOREHEAD, C.A. | SGT | R191109 | P | Uninj. |
| SLADE, B. GB | LAC | 1605868 | NAV | Uninj. |
| WARDER, A.J. GB | LAC | 160104 | AB | Uninj. |
| PUFALL, J.H. | CPL | 1205665 | WO | Uninj. |

SIGNAL: NO. No sig; DATE

D 14 (REVISED): NO. 1; CHECKED

#4

| ENGINE | ENGINE NUMBER (S) |
|---|---|
| Cheetah IX | 408621/AS37438 Nil |
| | A175633/AS30114 Nil |

HOURS FLOWN BY PILOTS

| INST. | NIGHT | ON TYPE SOLO | ON TYPE DUAL | TOTAL SOLO | TOTAL DUAL |
|---|---|---|---|---|---|
| 47 | 44 | 271 | 116 | 311 | 151 |

TYPE OF A/C | TYPE OF UNIT | CATEGORY

COMMAND | MONTH | STAGE OF FLIGHT

FORCED LANDING | TAXYING | LANDING | TAKE-OFF | FLIGHT | STAT'RY | INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Night navigation exercise.

NATURE OF ACCIDENT:

Engines and engine controls normal before failure. Stbd motor rough after 15 minutes flying.

TECHNICAL OFFICER'S REPORT:

Exhaust valves burned. No. 1 and 2 cylinders, stbd engine.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43