CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 14588

Title: Fairchild Cornell Cornell III serial:14588 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-June-19. Cornell II s/n 14588. This accident involved 1 person. Whortley WH

Keywords: RCAFCornell II,14588,24 EFTS,24 Elementary Flying Training School,Lynden Wash,1944-June-19,WhortleyRCAF L20

Created: 1944-06-19

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#14588

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
24 E.F.T.S. Abbotsford, B.C.	4	42 M. W. of Lynden, Wash., U.S.A.	19-6-44	1115

H.Q. FILE

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
CORNELL II	14588	~~1/2~~ E	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Whortley, W.H.	F/O	J16649	PP	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
	✓

#26

ENGINE	ENGINE NUMBER (S)
Ranger	27152/3043 Serious

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
4	2	17	31	17	31

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Routine Solo Training Flight.

NATURE OF ACCIDENT:

Motor failed at 1500 ft.- rough running of engine and missing - accompanied by a loud clatter. Student made a successful F/L after measures to restart the engine failed.

TECHNICAL OFFICER'S REPORT:

Technical failure of engine.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

Nil.

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43